

Division of Oil, Gas, & Mining  
Mining Report

01/16/97

MINE ID: M0150030

MINE NAME: SINBAD MINE

OPERATOR: SINBAD MINING CORP.  
CONTACT: MR. W.L. WILSON  
ADDRESS: 101 S 3RD ST STE 101  
GRAND JUNCTION CO 81501

PHONE: (303)243-7806

Surface Owner: BLM  
Mineral Owner: BLM

BLM #:  
Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
		SW				35	22.0S	10.0E

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: U

Mine Status: REC

Acreage: 0

Status Date: / /

Minerals Mined  
U

DATE  
RECEIVED

TENTATIVE APPROVAL  
DATE

FINAL APPROVAL  
DATE

LAST INSPECTED

12/24/79

02/28/80

04/07/80

10/18/95

BOND TYPE: SURETY BOND

BOND AMOUNT: \$\$\$\$16,225

ANNUAL REPORT YEAR: 96

	YTD	Total					
NONCOMP NOTICES:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/
VIOLATIONS:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/
REVISIONS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/
AMENDMENTS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/

COMMENTS:

MRC ORIGINALLY PERMITTED THIS SITE. THE NOI WAS TRANSFERRED TO THE CLAIM HOLDER (BILL WILSON) IN THE FALL OF 1982 WHEN THE MINE WENT ON STANDBY. INTERIM RECLAMATION WORK WAS PERFORMED AT THIS TIME ALSO. THE MINE WAS REOPENED BY A LESSEE IN LATE 1985. IT APPEARS THAT THE MINE MAY AGAIN BE ON STANDBY. 1992 REPORT STATES THAT @2 ACRES ARE DISTURBED. MINE STILL ON STANDBY STATUS. 1993 REPORT STATES THAT @1 ACRE IS DISTURBED. CLEANED UP TRASH & REMOVED MINE BUILDING IN 1993. UNKNOWN FUTURE OF MINE. INSP 10/95 FOR RECLAMATION DETAIL